EXCLUSIVE RESIDENTIAL REPORT

RESIDENTIAL Report

7111 Wolf River Ave.

Las Vegas

NV. 89131

21/Jan/2017

CC-201701007

EXAMPLE

SHAMROCK HOME INSPECTION CO. Las Vegas, NV LIC# 000-23-00-RES shamrock.hsnv@gmail.com www.shamrockhsnv.com

702-978-0170

EXCLUSIVE RESIDENTIAL REPORT





INSPECTION REPORT



INSPECTION PROPERTY ADDRESS: 7111 Wolf River Ave.

CITY: Las Vegas

STATE: NV. ZIP: 89131

THIS CONFIDENTIAL REPORT IS PREPARED EXCLUSIVELY FOR:

PREPARED BY: JEK

PROPERTY INSPECTED BY:

John E. Koen

LIC#: 000-23-00-RES









Please review your report thoroughly!

This report is the exclusive property of Shamrock Building Inspection Company, and the client whose name appears herein.

Use or release of the findings of this report by any unauthorized persons is strictly prohibited.





INSPECTION No. CC-201701007

TABLE OF CONTENTS

TABLE OF CONTENTS		Page 1.
DEFINITIONS		Page 2.
GENERAL INFORMATION		Page 2.
JUST TO CLARIFY		Page 3.
SCOPE OF INSPECTION		Page 4.
UTILITIES	SECITION I	Page 5.
GROUNDS/ LOT	SECTION II	Page 6.
EXTERIORS	SECTION III	Page 7.
ROOF	SECTION IV	Page 9.
GARAGE CAR OFT ELECTRICAL	ÉCIL	Page 11.
ELECTRAL	ECTION 1	Page 13.
PLUMBING	SECTION VII	Page 16.
APPLIANCES	SECTION VIII	Page 18.
INTERIORS	SECTION IX	Page 19.
STRUCTURE	SECTION X	Page 21.
HVAC/ COOLING	SECTION XI	Page 24.
FIRE PLACE	APPENDIX A	Page 26.
POOL/SPA	APPENDIX B	Page 29.
SUMMARY OF CHARGES	APPENDIX C	Page 37.
CLOSINING/ RECIEPT		Page 38.



shamrock.hsnv@gmail.com www.shamrockhsnv.com

INSPECTION No.

CC-201701007

Page. 2

DEFINITIONS

All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection. All comments by the inspector should be considered before a final decision is reached. Any recommendations by the inspector to repair or replace a specific component suggest a second opinion or further inspection by a licensed professional or contractor.

profess	sional of	contractor.	Note I: Photos with a red arrow show areas of concern.	
	A	ACCEPTABLE	Functional with no obvious signs of defect at time of inspection, if no other comments were made then item is functioning as intended allowing for normal wear and tear. (Indicated by a GREEN Box)	
	M	MARGINAL	Item is not fully functional and or requires service or repair. (Indicated by an AMBER Box)	
	D	DEFECTIVE	Item needs immediate repair or replacement. It is <u>unusable</u> and does not perform its intended function. (Indicated by a RED Box)	
	NI	NOT INSPECTED	Item was <u>unable</u> to be inspected for either safety reasons, lack- of power, inaccessibility, or disconnected at time of inspection. (Reason for <i>Non-Inspection</i> will be stated)	
CENT	N/A	NOT A LIVA E	Tem is not part of the studence and an does not fall under the scope of inspect of	
GENERAL INFORMATION				
CLIE	NT INF	ORMATION:	CLIENTS AGENT INFORMATION:	

PROPERTY INFORMATION Address: 7111 Wolf River Ave. 21/Jan/2017 **Date of Inspection:** City: Las Vegas **Time of Inspection:** 9:00 AM **State:** NV. **Zip:** 89131 1:30 PM **Inspection completed:** Temp: 44' F • Weather: Cloudy Ground/ Soil Surface Condition: Damp **Square Feet:** 3,867 **Year Built:** 2004 Front Facing: North Building Characteristics: ✓ Single Family Multifamily Town Home/Condo Other Levels: ___ 1 Story __ 2 Story __ 3 Story __ Other Remark(s): _____ Bedroom(s): 4 Bathroom(s): $5 \frac{1}{2}$ **Remark(s):** _____ Foundation Type: ✓ Slab Crawl Space/ Post & Beam Basement Combination Property: ___ Vacant ___ Unoccupied ✓ Occupied Remark(s): ____ Gated Community: Yes No Pets at property: No Yes (Secured? Yes




INSPECTION No.

CC-201701007


Page. 3.

JUST FOR CLARITY

Not all Inspected properties are set on their prospective lots in the same manor.




Second, some properties such as Condos and or Town Homes may not even have their own Lot to sit on.



In many cases it has come to this company's attention that when certain areas of the inspected property is being called out (**Right side**, **Left Side**, **etc.**), that there may be a small amount of confusion.

In order to clarify any confusion in the context of this inspection, when the inspector is referring to a specific area or hemit the extitle property it is in a feit no to the local of the front door of the property and NOT the local of the property is attituded.

Example:




Front or Front Yard

In the case of a Vacant Lot Inspection, the inspection will be in reference to how the Lot faces the main or

he Exception:

Access Street.



Main Street

In short imagine yourself as the property in question;

What side is your right side



and what side is your left?





INSPECTION No. CC-201701007

Page. 4.

SCOPE OF INSPECTION

The purpose of this inspection to perform limited, visual and auditory on site observations of the readily accessible areas of the primary structure, mechanical, and electrical systems of the building and give a **PERSONAL OPINION** as to whether or not the components of the building are performing the function(s) for which they were intended or in need of immediate repair. This report is not all encompassing, nor is it meant to be. It is very specific in the areas which are reported by the home inspector.

Please remember that almost every item in any house, except a brand new one, is in used condition and has ordinary wear and tear. Please also remember that older houses do not meet the same standards as newer houses, even though items in both might be performing functions for which they are intended.

We do not inspect any items we cannot see in a normal inspection. For example, we do not move furniture, rugs, paintings, flooring, etc. Repairs or remodeling may hide evidence of prior damage or defects. We do not dismantle equipment to inspect component parts. We do suggest that YOU ask the seller about repairs, covered up items, or previous problems.

We do not hold ourselves to be specialists for any particular item. We are a general inspection company. If we report an item is not inspected, not performing its intended function or needs repair, we urge you to have that item examined by a specialist before purchasing the property.

The components of major systems and standards of conduct of the inspection are governed by "Standards of Practice for Home Inspection Report" by the American Society of Home Inspectors, Copyright 1993, and by the National Association of Home Inspectors, Copyright 1990. While many aspects of each component are inspected, for ease and clarity of reporting, not all are defined and described in complete detail on the written report.

It should be understood that we do not offer or supply any warranty, guarantee or insurance policy with regard to the continued soundness of construction, the user fire accuracy, future perfect ances as a potential defect of any items inspected; or operability of equipment or appliance. It should be understood to to the application of construction, plumbing, electrical, mechanical desimilar coordand or ances and that the inspector's written report is the inspector's subjective determination of the condition of such mems at me time the inspection was made. Estimates of age of any components are approximate, and the design life of a component is determined according to manufactures' specifications.

The term "inspection" **DOES NOT** include all items. Specific items which are not part of the inspection include, but are not limited to: lead paint, asbestos, radon, toxic or flammable materials, refrigerators, freezers, remote overhead door transmitters/receivers, floor coverings, wall coverings, free standing kitchen appliances, laundry appliances, water conditioners, underground storage tanks, driveway, tennis courts, playground equipment, Bar-B-Q Grills, or other recreational or leisure appliances, and self-cleaning or continuous-cleaning capabilities of ovens. Also excluded is an inspection for any non-wood infesting insects, such as flees, cockroaches, bees, mites, ticks, flies, etc. A separate wood destroying inspection report, and radon sampling will need to be contracted separately.

If you have any complaints about our inspection, you must notify us in writing within seven (7) days after you discover any problems and let us re-inspect before changing the condition of the item, except in emergencies, of course. If the repairs are made before the inspection company re-inspects the problem, then any claims against the inspection company's failure to adequately inspect such item is waived. No suit or action shall be brought against the inspection company by any third party at any time beyond 1 year after the accrual of the cause of the action itself. If someone other than the client who ordered this inspection shall make any claim or file any lawsuit against the inspection company for failure of its services hereunder in any respect, the client agrees to indemnify, absolve and hold harmless the inspection company from any and all such claims and lawsuits including the payment of all damages, expenses, cost and attorneys' fees. Should a party make any claim or file any lawsuit against the inspection company, such party shall pay all damages, expenses, costs and attorney fees of the inspection company if the complaint party does not win.

This report was furnished at the request of the client, by the inspection company in determining the overall condition of the subject premises. Furthermore, this report is not to be used for determining the value of the premises or whether same should be purchased. **NEITHER IS IT TO BE CONSTRUED AS A GUARANTEE OR WARRANTY OF THE PREMISES** or the equipment therein or of their fitness for specific use.

We certify that our inspectors have no interest, present or contemplated, in the property or its improvements, and no involvement with tradespeople or benefits derived from any sales or improvements made to this property. It is the clients right to hire more than one inspector, different inspectors can find different things sometimes on the same home. My inspection company is not responsible for any discoveries included or not found. As this inspection report ages, the condition of this home and its components can change.



INSPECTION No.

CC-201701007

Page	5	
	_	۰

UTILITIES SECTION I This inspection is not intended to address or include any areas of the utilities installation nor activation. If the NI - Not Isnpected utilities are off and unavailable during the time of inspection, many portions of this report may not be possible. If M - Marginal Defective utilities are locked and unavailable the inspection team will not attempt to activate, turn on, or initiate the utilities. This is a visual inspection, any portions that is not visible and or not readily accessible will not be inspected. If Utilities and or services are inactive and sealed, either by the city or owner of the property, the inspection team may continue the investigation taking in all safety considerations. If the inspector witness a hazardous, Emergency and or safety concern they will shut off any utilities, and notify the proper services and the client immediately. a. GAS METER D NI NA On Off Locked Remark(s) Service Provider: City Private Main Gas Valve Location: Left Side M D NI NA b. WATER METER On Off Locked Remark(s) Service Provider: City Front Right Main Water Meter Location: ✓ City **SEWER SERVICE:** Private – Type: Note II: Most main service cables are Underground and unavailable for inspection, Recommend a further inspection by a licensed electrician. c. MAIN ELECTICAL PANEL Off NI NA On Locked Adequate Clearance to Panel: Yes No Year: 2004 Manufacturer: Square D Conductors: Amps: | 240 Copper Aluminum Main Wire Copper Aluminum Not Visible Ground Wire: Yes No Not Visible Remark(s) Main Elec. Panel Location: Left Side Private – Type: SERVICE PROVIDER: City

Note III: Solar System are a closed system and outside the scope of the inspector's expertise, contact the system installer and or provider for further evaluation of the system.

No

Yes

SOLAR SYSTEM:



INSPECTION No.

CC-201701007

www.shamrockhsnv.com

Page. 5a.

PHOTO(s) SECTION I



Gas Service In (OK)



Bonding (OK)



Analog

EXAMPLE



Water Meter Cover



City Shut Off



Home Shut Off



Breakers (OK)



Uppers (OK)



Lowers (OK)



shamrock.hsnv@gmail.com www.shamrockhsnv.com

INSPECTION No.

CC-201701007

Page. 6.

GROUNDS/ LOT	SECTION II
This inspection is not intended to address or include any geological conformation concerning these conditions, a geologist or soils engineer limited to only areas around the exterior of the exposed areas of the formula of the exposed areas of the	should be consulted. Any reference to grade is condation or exterior walls. This inspections nee of the site or the condition of any eptic system. Decks and porches are often built eas as well as others too low to enter, or in some enter addressed in this report. We routinely
M D NI NA a. DRIVEWAY Type:	
T W I I WALK WAY	
M D NI NA b. WALK WAY Type:	
M D NI NA c. GRADING/ LANDSCAPING/ DRAINAGE (FRONT)	
THE RESIDENCE OF A DISCOVERING A DESCRIPTION OF A SECTION OF A DESCRIPTION	
M D NI NA d. GRADING/ LANDSCAPING/ DRAINAGE (LEFT)	
M D NI NA e. GRADING/ LA DSCAP. 3/ DRAIN GE (II. HT)	
M D NI NA f. GRADING/ LANDSCAPING/ DRAINAGE (REAR)	
M D NI NA g. RETAINING WALL(s) 1 Number: Location: Re	ar & Right Front
M D NI NA h. GATE(S) 6 Number: Type: 1-RV (Gate/ 4-Pool/ 1-Ac Side Yard.
Location(s): Back Yard	2000 1120 2100 1010.
M D NI NA i. FENCE Block Type: Location:	Back Yard
M D NI NA j. IRRIGATION SYSTEM (FRONT) Type: Metered Drip	
T Senindation	
M D NI NA k. IRRIGATION SYSTEM (REAR) Type: Sprinkler	

REMARKS:



INSPECTION No.

CC-201701007

Page. 6a.

PHOTO(s)





Driveway (OK)



Walk Way (OK)




Front Yard (OK)

EXAMPLE



Retaining Walls (OKO



Right Side (OK)



Left RV Parking (OK)



Back Yard (OK)



Irrigation System (OK)



Back Patio (OK)

Note: BBQ and Beer Cooler r just need cleaning.



shamrock.hsnv@gmail.com www.shamrockhsnv.com

INSPECTION No. CC-201701007

Page. 7.

EXTERIOR/BUILDING SECTION III Areas hidden from view by finished walls or stored items cannot be inspected or evaluated, and are not a part of this Isnpected Not Appicable inspection. Minor cracks are typical in many foundations and most do not represent a structural problem. If major Marginal D - Defective cracks are present along with bowing, we routinely recommend further evaluation be made by a qualified structural engineer. All exterior grades should allow for surface and roof water to flow away from the foundation. All concrete Not.] floor slabs experience some degree of cracking due to shrinkage in the drying process. In most instances floor Į. coverings prevent recognition of cracks or settlement in all but the most severe cases. Where carpeting and other AA Σ floor coverings are installed, the materials and condition of the flooring underneath cannot be determined. NI NA a. FRONT STEP/ STAIRS Type: Concrete MARGINAL, Item may require service and or repair at a later time. b. FRONT PORCH/ STOOP NI NA Type: Concrete D Duel W/ Glass Panel. D NI NA c. FRONT DOOR Type: d. FRONT/ ENTRY OVERHANG D NI NA D NI NA e. BUILDING NUMBER Visible from street: Yes Illuminated: Yes NI NA f. FRONT W D ADC WE Num Type: Duel Pane g. FRONT WALLS/ SIDING h. LEFT WINDOWS D NI 🔼 Number: Type: i. LEFT WALLS/ SIDING Type: Duel Pane NI NA Type: Duel Pane D NI NA j. REAR WINDOWS 14 Number: M D NI NA k. REAR WALLS/ SIDING Type: Duel Pane D NI NA I. RIGHT WINDOWS Type: Duel Pane Number: NI NA m. RIGHT WALLS/ SIDING Type:Duel Pane D n. REAR OVERHANG/ ATTACHED PATIO COVER * Note: Not Part of a Deck.



shamrock.hsnv@gmail.com www.shamrockhsnv.com

INSPECTION No.

CC-201701007

Page. 8.

NV - 20151491056

EXTERIOR/ BUILDING/ GARAGE **SECTION III** Determining the heat resistance rating of fire walls is beyond the scope of this inspection. Flammable materials NI - Not Isnpected should not be stored within closed garage areas. D - Defective M - Marginal TYPE: ✓ Attached __ Unattached NUMBER DOORS: 2 NUMBER OF VEHICLES STRUCTURE CAN ACCOMMODATE: 3 - CAR ATTIC ACCESS: ___ Yes ___ No ✓ Finished ___ Unfinished M D NI NA o. GARAGE WINDOW(s) Number Type: 12 in Doors M D NI NA p. GARAGE WALLS/ SIDING Type: Stucco M D NI NA q. GARAGE DOOR(s) Number Type: Roll Up r. GARAGE OVERHANG (I/A) A M D NI PHOTO(s)





Front



Front/ Left



Rear/ Right



Rear



Rear/ Left

shamrock.hsnv@gmail.com www.shamrockhsnv.com

INSPECTION No.

CC-201701007

Page. 8a.

PHOTO(s)



Settling Cracks @ Riser Joints for each of the front stairs.



Front Stoop (OK)



SECTION III

Front Door (OK)




Right Walls (OK)



Front Windows (OK)




Entry Overhang (OK)



Patio Cover Right (OK)



Building # (OK)



Patio Cover Left (OK)



shamrock.hsnv@gmail.com www.shamrockhsnv.com

INSPECTION No. CC-201701007

	ige.							
R	OC	F			SECTION IV			
A - Acceptable	M - Marginal	D - Defective	NI - Not Isnpected	NA - Not Appicable	The following is an opinion of the general quality and condition of the roofing material. The inspector cannot and does not offer an opinion or warranty as to whether the roof leaks or may be subject to future leakage. This report is issued in consideration of the foregoing disclaimer. The only way to determine if a roof is absolutely water tight is to observe it during a prolonged rainfall. Many times this situation is not present during the inspection. This inspection is made on the			
	M	D	NI	NA	a. ROOF Type: Hip Covering: Tile (S) Pitch: 4 /12			
_	141	D	INI	1424	Method of Inspection: On Approximate Age: 12 years			
					Approximate Age. 12 years			
				l				
	M	D	NI	NA	b. CONDITION The Inspector is NOT authorized to remove and or repair any items or damage found on the roof.			
					Debris on Roof: ✓ No Yes			
					Physical Damage: ✓ No Yes Two Cracked Tiles			
					Structural Deformation: ✓ No Yes			
Α	M	D	NI	N	c. SKY LIGHT(s) Number: Type:			
	M	D	NI	NA	d. CHIMNEY(s) Num, T: Tpe -vie I			
1					In Conjunction ith - V ire Play V bile O he			
					Spark Arrestor: ✓ Yes No Capped Off: Yes ✓ No			
	M	D	NI	NA	e. FLASHING Not Visible Type: Galvanized			
					Signs of Damage: ✓ No Yes			
					Signs of corrosion: ✓ No Yes			
	M	D	NII	NΛ	f. PLUMBING VENT(s) Number: 12 Type: PVC			
_	M	U	NI	INA	Signs of Damage: V No Yes			
					Signs of Damage. V 140 1 165			
	M	D	NI	NA	g. EXHAUST VENT(s) Number: 14 Type: Galvanized			
					Signs of Damage: ✓ No Yes			
				1	Signs of corrosion: ✓ No Yes			
				1				
Α	M	D	NI	N.	h. GUTTERS/ DOWN SPOUTS Number: Type:			
					Signs of Damage: No Yes			
				ł	Signs of corrosion: No Yes			



shamrock.hsnv@gmail.com www.shamrockhsnv.com

INSPECTION No.

CC-201701007

Page. 10. **ROOF SECTION IV** i. VENTILATION Envelope D NI 🔼 Soffit Ridge Gable Other: Signs of Damage: No Yes Signs of corrosion: No Yes 2 x 8 D NI NA j. FACIA (FRONT) Not Visible Covered Type: Size: Signs of Damage: M D NI NA k. SOFFIT (FRONT) Not Visible Type of covering: Stucco Signs of Damage: ✓ Yes No 2 x 8 M D NI NA I. FACIA (LEFT) Not Visible Covered Size: Type: Signs of Damage: ✓ No Yes D NI NA m. SOFFIT (LE Stucco rering: Signs of Size: 2×8 n. FACIA (REAR) Not Visible Type: Covered Signs of Damage: Yes Not Visible D NI NA o. SOFFIT (REAR) Type of covering: Stucco M Signs of Damage: Yes D NI NA p. FACIA (RIGHT) Not Visible Covered Size: 2 x 8 M Type: Signs of Damage: ✓ No Yes M D NI NA q. SOFFIT (RIGHT) Not Visible Type of covering: Signs of Damage: ✓ No Yes Webs Top chord Roofing Roof batten Web tie Pitching point (web brace) Pitch Rafter Fascia Pitching point Nailplates Ceiling Ceiling batten Bottom chord Overhang Cantilever Overhang Wall Cantilever web Bottom chord tie Gutte Nominal span Overall length



INSPECTION No. CC-201701007

Page. 10a.

PHOTO(s)




SECTION IV



Roof Covering in Acceptable Condition

Cracked Tile









Facia and Soffits (OK)



shamrock.hsnv@gmail.com www.shamrockhsnv.com

INSPECTION No. CC-201701007

Page. 11.

GARAGE	SECTION V
A - Acceptable M - Marginal D - Defective NI - Not Isnpected NA - Not Appicable	Determining the heat resistance rating of fire walls is beyond the scope of this inspection. Flammable materials should not be stored within closed garage areas. TYPE: Attached Unattached NUMBER DOORS: 2 NUMBER OF VEHICLES STRUCTURE CAN ACCOMMODATE: 3 - CAR Finished Unfinished ATTIC ACCESS: Yes No
M D NI NA	a. GARAGE DOORS (INSIDE) Type: Roll Up Number: 2
M D NI NA	
M D NI NA	c. GARAGE ACCESS DOOR (TO RESIDENCE) Type: Fire Rated Self-Closing: Yes
M D NI NA	d. GARACE ACCES TO YARD Type: Standard Location: Left Side
A D NI NA	e. GARAGE CEILING (FINISHED) Separation in Joint Tape/ Compound in Front section of Garage Ceiling.
M D NI NA	EVANADIE
M D NI NA	h. WALLS (INCLUDING FIREWALL SEPARATION)
M D NI NA	i. GARAGE FLOORS Material: Concrete
M D NI NA	j. GARAGE DOOR OPENER #1 (I/A.) Manufacturer: Chamberlain # Remotes: 1
M D NI NA	k. GARAGE DOOR OPENER #2 (I/A.) Manufacturer: Chamberlain # Remotes: 1
A M D NI	I. GARAGE DOOR OPENER #3 (I/A.) Manufacturer: # Remotes:
A M D NI	m. GARAGE DOOR OPENER #4 (I/A.) Manufacturer: # Remotes:

shamrock.hsnv@gmail.com www.shamrockhsnv.com

INSPECTION No.

CC-201701007

Page. 11a.

PHOTO(s)





Garage Ceiling



Garage Door #1 (OK)



SECTION V

Garge Door #2 (OK)


EXAMPLE




Access to Storage Room




Yard Access (OK)




Access to Home (OK)



Ceiling (OK)



Walls (OK)



Floors (OK)



shamrock.hsnv@gmail.com www.shamrockhsnv.com

INSPECTION No. CC-201701007

		12.								
CA	١R	PO	DRT						SF	ECTION V
A - Acceptable	M - Marginal	D - Defective	NI - Not Isnpected	home the carport being investigated section to the clie	is maintained is a condo, nt. Stucco F VEHIC	d by the HOA and town home or hig Metal LES STRUC	does not fall us h rise this section Exposed	nder the scope on (Garage ad Frame	if this investig or carport will Other:_	andominium and or town gation. If the structure be considered a curtesy
Α	M	D	NI N	n. CARPORT/ OVE	RHANG	Attached	No	t Attached	Size:	
)	T. C	g ·			
Α	M	D	NI N	o. CAR PORT ROC	OF (TOP)	Type of	Covering:			
Α	M	D	NI 1	p. CAR PORT CEIL	ING					
A	M	D	NI I	q. CAR PORT BEA	MS					
			141 /-	q. ozar i or		7	/IT		T	
						AII		4	P.	
Α	M	D	NI N	r. CAR PORT . OST			<u> </u>			
Α	M	D	NI N	A s. FLOORS	Mater	rial:				
	1	- 1	1		TO DECIDE	-NOE ((A)	T.		0.100	
Α	M	D	NI 1	t. ACCESS DOOR	TO RESIDE	ENCE (I/A)	Type:		Self-C	losing:
CA	۱R	PO	DRT						PI	HOTOs (I/A)
				icture Available lot Applicable		No Pictur If Not A _l	e Available oplicable		,	No Picture Available If Not Applicable





INSPECTION No. CC-201701007

Page. 13.

ELECTRICAL SECTION VI

This report addresses the primary electrical power distribution system serving the building. Any electrical repairs attempted by anyone other than a licensed electrician should be approached with extreme caution. The power to the entire house should be turned off prior to beginning any repair efforts, no matter how trivial the repair may seem. Aluminum wiring requires periodic inspection and maintenance b a licensed electrician. The operation or condition of any time clock motor is NOT verified. Inoperative light fixtures often lack bulbs or have dead bulbs installed. Light bulbs are not changed during the inspection. Any ceiling fans are checked for general operation only. Smoke alarms should be installed on all levels of the home and within 5 feet of all bedroom doors. Smoke alarms and carbon monoxide detectors should be tested regularly. Security alarm systems and their components are NOT addressed by this inspection. We recommend you consult the alarm monitoring company for further information.

A - M - D - D - NI	alarms should be installed on all levels of the home and within 5 feet of all bedroom doors. Smoke alarms and carbon monoxide detectors should be tested regularly. Security alarm systems and their components are NOT addressed by this inspection. We recommend you consult the alarm monitoring company for further information.
M D NI NA	MAIN SERVICE PANNEL ** See Utilities section for main service panel **
M D NI NA CAMPAING CACCORD SHOCK This applicant is to be a varied by the beautiful or by A WARNING CACCORD SHOCK This applicant is to be presented drip.	a. SUB-ELECTICAL PANEL ✓ On Off Locked Adequate Clearance to Panel: ✓ Yes No Manufacturer: Square D Year: 2004 Conductors: ✓ Copper Aluminum Amps: 240 Main Wire ✓ Copper Aluminum Not Visible Ground Wire: ✓ Yes No Not Visible
M D NI NA	Remark(s) Sub- Elec. Panel Location: Garage b. DOOR BELL
M D NI NA	c. ENTRY LIGHT
M D NI NA	d. EXTERIOR LIGHTING Type: On Photo Cell Location: Front Gaurge
M D NI NA	# Not working 0 Location(s): # Missing Weather Covers: 0 Location(s):
M D NI NA	f. GARAGE LIGHTING Number: 4 Type: Fluorescent # Not working 0 Location(s):
M D NI NA	# Not working Uccation(s): Standard
M D NI NA	h. GARAGE OUTLETS Number: 7 G.F.C.I. Protected: Yes # Not working U Location(s):





INSPECTION No. **CC-201701007**

Page. 14.

ELECTRICA	AL	SECTION VI
M D NI NA	i. LIGHTS MOUNTED - FIRST FLOOR (Including Ceiling Fans)	* This also includes Recessed Can Lights)
	Number Lights: 41 # Not Working: 0	<u> </u>
	Locations:	
	Number Ceiling Fans: 9 # With Light Kits: 9	# Not Working: 0
	Location(s):	
	# Mounted Bathroom Lights: 11 # Not Working: 0	
	Location(s):	
- 14 15 15 17 14 1	j.1st FLOOR SWITCHES Number: 35 Type: Star	ıdard
M D NI NA	# Not working Location(s):	ldai d
A D NI NA		
		chen GFCI Near REF.
	# G.F.C.I. Outlets (Kitchen/ Bathrooms/ ETC.): 20 # Not	working: 0
A M D NI	I. LIGHTS MOUNTED - SECOND FLOOR (Including Ceiling Fans)	* This also includes Recessed Can Lights)
	Number Lights: Not Working:	
	Locations:	H
	Number Ceiling Pane: "With Dight Kits:	"Not Working:
	Location(s):	
	# Mounted Bathroom Lights: # Not Working:	
	Location(s):	
	m.2 ND FLOOR SWITCHES Number: Type:	
A M D NI	m.2 ND FLOOR SWITCHES Number: Type: # Not working Location(s):	
A M D NI	n. 2 ND FLOOR OUTLETS Number: Method Teste	d:
	# Not working Location(s):	1.
	# G.F.C.I. Outlets (Kitchen/ Bathrooms/ ETC.): # Not	working:
A M D NI	o. LIGHTS MOUNTED - THIRD FLOOR (Including Ceiling Fans)	* This also includes Recessed Can Lights)
	Number Lights: # Not Working:	
	Locations:	
	Number Ceiling Fans: # With Light Kits:	# Not Working:
	Location(s):	
	# Mounted Bathroom Lights: # Not Working:	
	Location(s):	
A M D NI	p. 3 RD FLOOR SWITCHES Number: Type:	
A M D NI	# Not working Location(s):	
	V / V	



shamrock.hsnv@gmail.com www.shamrockhsnv.com

INSPECTION No. **CC-201701007**

ELECTRICA	AL SECTION VI
A M D NI	q. 3 RD FLOOR OUTLETS Number: Method Tested:
	# Not working Location(s):
	# G.F.C.I. Outlets (Kitchen/ Bathrooms/ ETC.): # Not working:
M D NI NA	r. LIGHTS MOUNTED-ATTIC Attic Access Location: Laundry Room / Front Guest Bathroom
M D NI NA	s. ATTIC SWITCHES Number: 3 Type: Standard
	# Not working 0 Location(s):
M D NI NA	
	# Not working 0 Location(s):
A M D NI	
	Number Lights: # Not Woking: Locations:
	Number Ceiling, answard #Wi Light (its #N)t orbitg:
	Location(s):
	# Mounted Bathroom Lights: # Not Working:
	Location(s):
A M D NI	v. BASEMENT SWITCHES Number: Type:
	# Not working Location(s):
A M D NI	w. BASEMENT OUTLETS Number: Method Tested:
	# Not working Location(s):
	# G.F.C.I. Outlets (Kitchen/ Bathrooms/ ETC.): # Not working:
M D NI NA	x. SMOKE/ CARBON MONOXIDE DETECTOR (1st Floor) Number: 12 Wired to Elec. YES
	# Not working Location(s):
A M D NI	y. SMOKE/ CARBON MONOXIDE DETECTOR (2 nd Floor) Number: Wired to Elec.
	# Not working Location(s):
A M D NI	z. SMOKE/ CARBON MONOXIDE DETECTOR (3 rd Floor) Number: Wired to Elec.
	# Not working Location(s):
A M D NI	xx. SMOKE/ CARBON MONOXIDE DETECTOR (Basement) Number: Wired to Elec.
	# Not working Location(s):

INSPECTION No. **CC-201701007**

Page. 15a.

PHOTO(s)





Exterior Outlets (OK)




Door Bell (OK)



Exterior Lights (OK)





Ceiling Fans (OK)



Ceiling Lights (OK)



Switches (OK)

INSPECTION No.

CC-201701007

SECTION VI

Page. 15b.

PHOTO(s)





Most Interior Outlets are working properly. (Tree Outlets in front Laundry Room are non-operational)







EXAMPLE







Kitchen GFCI Not tripping





INSPECTION No. CC-201701007

Page. 16.		
PLUMBING		SECTION VII
or corrosion in u determine wheth water supply. The laboratory testin lines in an attice verified. It is beginned to the surrounding man	nderground piping cannot er water supply and waste to operational effectiveness g. We recommend you verior structure is limited to are yound the scope of a visual iterials where tile damage of	pply, waste, or sprinkler use are excluded from this inspection. Leakage be detected by visual inspection. It is not within the scope of this report to disposal systems are public or private, the quantity and quality of the of any installed water treatment equipment cannot be determined without fify these items with the seller. Determination of leakage at water supply has where pipes are accessible. Operation of time clock motors is not enspection to determine the total extent of damage to underlying or moisture intrusion is present. Safety and shut-off valves are not operated quent leakage, unless in an emergency situation.
A M D NI NA MAIN WATER ME	TER	** See Utilities section for main water meter **
		times they are Underground/ Inside Walls/or Covered by insolation.
WATER PREASURE (psi): 32 psi		OUTSIDE TEMP AT TEST: 44' F °
M D NI NA a. MAIN WATER S	HUT OFF VALVE I	ocation: Garage
<u> </u>	L	1 - 10
<u> </u>		
M D NI NA b. SERVICE CAPS/	CLEAN OUTS Number	r: 2 Location: Back Wall
M D NI NA C. EXTERIOR WAT	ER SPICKETS Number	r: 5 # Missing Anti Backflow Valve 0
M D NI NA d. EXERIOR DRAIN	S Number: 2	Location: Front Yard
- M D DUM - IRRICATION CV	TEN	
M D NI NA e. IRRIGATION SY		on: 1 rage T sted: 22-Jan-2017
Automatic Tir		on: 1 rage T sted: 22-Jan-2017
Anti-Siphon va Lawn Sprinkt		
Lawn Sprinki	cis. 1 cs 1 j	pc. Kain Bird
M D NI NA f. Kitchen Water/	Drain Lines Evidence	e of leaks: No
Sink:	✓ Hot water ✓	Cold water Drains OK: Yes
) Minutes Drains OK: Yes
Refrigerator:	Connected to water line	
icenigeidioi.	Connected to water fille	Diams OK. ICC Warci
[
M D NI NA g. LAUNDRY ROO	M SERVICE/ DRAIN LINE	Location: Front Left Hallway
M D NI NA h. 1st FLR. ½ Bath	Water/ Drain Lines	Location: Front Riight Hallway
	✓ Hot water ✓	Cold water Drains OK: Yes
Tub/ Shower:	Hot water	Cold water Drains OK:
Toilet:	✓ Flush OK ✓	Fills OK Evidence of Leaks: No





Page. 17.

shamrock.hsnv@gmail.com www.shamrockhsnv.com

INSPECTION No. CC-201701007

PLUMBING							S	ECTION VII
M D NI NA	i. Family Bath 1	- Wat	er/ Drain Lines	I	Location: Fr	ont Room (Right	Side)	
	Sink:	✓	Hot water	√	Cold water	Drains OK:	Yes	
	Tub/ Shower:	✓	Hot water	✓	Cold water	Drains OK:	Yes	
	Toilet:	✓	Flush OK		Fills OK	Evidence of L	eaks:	No
M D NI NA	j. Family Bath 2	- Wat	er/ Drain Lines	I	Location: From	ont Room (Left S	Side)	
	Sink:		Hot water	√	Cold water	Drains OK:	Yes	
	Tub/ Shower:	✓	Hot water	√	Cold water	Drains OK:	Yes	
	Toilet:	1	Flush OK	1	Fills OK	Evidence of L	eaks:	No
	Sink Tub/ Shower Toilet	1	Ho vater (us) K	√	Cold feet old value feet feet feet feet feet feet feet fe	D ins OK D ins OK E dend o L	Yes	No
M D NI NA	l. Master Bath \	Water/	Drain Lines	Loca	tion: Rear	Left Side		
	Sink:	✓	Hot water	√	Cold water	Drains OK:	Yes	
	Tub/ Shower:	✓	Hot water	√	Cold water	Drains OK:	Yes	
	Toilet:	✓	Flush OK		Fills OK	Evidence of L	eaks:	No
M D NI NA	ml. WATER HEA	TER #:	1					
	Loc	ation:	Garage		Temperature:	120' F		
	Manufac	cturer:	Premium Plu	ıs	PSI:	32 psi	A PE	

M	D	NI	NA	ml. WATER HEATER #1			
				Location:	Garage	Temperature:	120' F
				Manufacturer:	Premium Plus	PSI:	32 psi
				Type:	Gas	Pilot Light:	ON
				Capacity:	80 U.S. Gallon		
				Approximate Age:	3 years		
				TPRV and Drain Tube:	Acceptable		
				Seismic Straps:	Acceptable	<u> </u>	





www.shamrockhsnv.com

INSPECTION No.

CC-201701007

Page. 17a.

PHOTO(s)

SECTION VII




Front Drain Clean Put



Exterior Spicket (OK)



Irrigation Control (OK)



Main Shut Off (OK)



Water Softener (OK)




Pool Shower (OK)



Kitchen (OK)



Bathrooms (OK)



Drains Clear (OK)



shamrock.hsnv@gmail.com www.shamrockhsnv.com

INSPECTION No. **CC-201701007**


Page. 18.

A	PP	LL	AN	CE	ES SECTION VIII						
A - Acceptable	M - Marginal	D - Defective	NI - Not Isnpected	NA - Not Appicable	Inspection of standalone freezers, Water Softener Systems, and built-in ice makers are outside the scope of this inspection. No opinion is offered as to adequacy of such items. Ovens self or continues cleaning operation, cooking functionality, clocks, timing devices, and thermostat accuracy are not tested during this inspection. Appliances are not moved or adjusted during the inspection. Portable Dishwashers are not inspected as they are not considered permanent fixture to the property and require additional set-up for operation. Note: Services such as Water, Gas and Electricity must be active in the building for the inspection to be completed, if no services are available only a spot check for damage and availability will be conducted.						
KI	TCI	HEI	N								
	M	D	NI	NA	a. RANGE/ COOKTOP Type: ✓ Gas Electric Propane						
					Manufacture: GE						
	M	D	NI	NA	b. OVEN #1 Type: ✓ Gas Electric Propane						
					Manufacture: GE All in One with Stove top: Stand Alone:						
	M	D	NI	NA	c. OVEN #2 Type: √ Gas Electric Propane						
			<u> </u>		Manufacture: GE						
	M	D	NI	NA	d. MICROWAVE OVEN Mounted in cabinet: Mounted Over Stove: ✓						
					Manufacture: GE						
	М	D	NI	NA	e. VENT HO D Styndam he que Stov : Iounted Difference Oven: \sqrt{\text{Manufacture:}} \sqrt{\text{GE}}						
	M	D	NI	NA	f. DISPOSAL Manufacture: Badger Switch Location: Top of Sink (L)						
		_			Parager Switch Zeedach 100 of Shik (E)						
	M	D	NI	NA	g. DISH WASHER Manufacture: GE Drain Air Loop: Working						
					OZ WORKING						
	M	D	NI	NA	h. REFRIGERATOR Manufacture: GE Interior Temp: 00' F/ 29' F						
_					01						
	M	D	NI	NA	i. KITCHEN SINK Type: Under Counter						
		_			-71" Onder Counter						
L/	/UN			_	ОМ						
	M	D	NI	NA	j. CLOTHES WASHER Manufacture: GE						
_			ı —								
	M	D	NI	NA							
					Manufacture: GE						

INSPECTION No. **CC-201701007**

Page 18a.





STOVE



MICROWAVE



REFRIGERATOR



STOVE (ON)



VENT HOOD



FREEZER



OVEN #1



DISPOSAL



REF. INTERIOR.



OVEN #2 7111 Wolf River Ave.



DISH WASHER



CLOTHES WASHER/DRYER

